

Figure 1: Front of Building



Figure 2: Driveway Side, From Front



*Figure 2: Partial Driveway Side*



*Figure 3: Partial Driveway Side View*



*Figure 5: Door Below Figure 4*



*Figure 6: Rear View*



*Figure 7: Rear View, Centre Section*



*Figure 8: Rear View, Centre Section. Note that eavestrough on narrow section has custom joint and that eavestrough carries sump pump hose. It would have to be removed and reinstalled after painting.*



*Figure 9: Side View (Covered Porch)*



*Figure 10: Side View (showing porch)*



*Figure 11: Underside of Porch, toward road*



*Figure 12: Underside of porch, away from road*



*Figure 13: Underside of porch, parallel to road*



*Figure 14: Close-up of shingle damage, driveway side*



*Figure 15: Example of shingle damage along driveway side and in limited areas of the centre section*



*Figure 16: Underside of driveway side wooden awning*



Figure 17: Close-up of bare area on Centre section



Figure 18: Front door area

