

APPENDIX E: PICTURES

SC 1 & SC 2, First three pictures show SC 1 and the worst of the flaking paint; volunteers can do some scraping to remove the worst of the flaking paint. Last two pictures show the sides of SC 2.



Training Facility: Exterior Views



Training Facility: Interior Views

Second picture is view through stairs to second floor, showing railing that must be painted.



Training Facility: Interior Views



Training Facility: Interior View

Shows the bottom of a bulkhead containing a door which is typical at two locations on the ground floor. The bulkheads create the vestibules shown in Sketch 1.



Sketch 1:

