

Appendix - Site Photographs

The following photographs of the former Clarksville School/Clarksville Community Hall were taken on August 16, 2021 by the Manager, Real Estate & Corporate Projects.



Exterior view of Subject Property from Clarksville Road



Exterior view of former school building and accessory building



View of entrance steps; evidence of wood rot and overgrown vegetation



View of entrance ramp; evidence of wood rot and overgrown vegetation



Interior view; evidence of water damaged building materials



Interior view; evidence of water damaged building materials



View of heating system (uncertified wood stove) and electrical panel (no power, requires upgrade)